B.R. No: 825/Date: 09/1/2015

Inspection report for the work of :_Maintenance of Borewells at abbigere & Medarahalli, in SSD,

in Ward no. 12

Chief Engineer

Dasarahalli zone

BBMP, Bangalore

Inspection Report

Name of Work	:	**Maintenance of Borewells at abbigere & Medarahalli, in SSD, in Ward no. 12**
Work Order	:	No. EE/DD/WO/ 258 /13-14, Dated: 15/02/2014
Agency	:	S. Prakash
B.R. No & Dated	:	825/Date: 09/1/2015
Bill Amount	:	Rs. 1498182.00
Job Code	:	012-14-000009
P. Code	:	P1771

Taking Photos 10.7.2015

The Location of the Borewell is inspected by me along with concerned Engineer and ascertained that as Borewell Maintenance work such as removing and refitting of G I pipeline in the Borewell for repair of the Motor as shown in the photo is Enclosed.

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು.

COMPLETION REPORT

(01)	Name of Work	:	Maintenance of Borewell of Abbugere abd Medharahalli in Ward No.12, Shettyhalli Sub Division.
(02)	Sanctioned estimate No. and Date	:	
(03).	Head of Account which is chargeable	:	P-1771-
(04)	Entrustment order No. and Date	:	EE/DD/250/258/14-15 dt 15.02.2014
(05)	Name of the Contractor	:	**SRI.S. PRAKASH, No.35/36, Gangamma Garden, Malagala Main Road, Nagarabhavi 2nd Stage, Bangalore-560 091.**
	a) Time stipulated for complete of the work.	:	90 days
	b) Delay in execution of work	:	-
(06)	Measurement recorded in	:	M.B. No. 1789/13-14. From Page No. 178861/1 to 178874/2.
(07)	Check measurement of the Assistant Executive Engineer / Executive Engineer on ……..	:	M.B. No. From Page No.
(08)	Name of the Officer / Official in charge of the work.	:	
(09)	Assistant ~~Executive~~ Engineer / Junior Engineer.	:	N.K. Ravi.
	b) Assistant Executive Engineer	:	B.L. Jayalingappa.

Sanctioned Estimate Amount	Amount claims as per actually viz., as per bill	Difference Excess	Difference Savings	Remarks
1500000=00	1498182=00.	-	1818	-

1. Certified that the above work has been completed within the stipulated time noted in the work order.
2. Certified that the contractor has delayed and completed the work for which necessary fine has been recovered.
3. Certified that the above work has been executed by the contractor satisfactorily in accordance with the specification as embodied in the agreement.

Ravi.N.K. 31/12/2014.
~~Junior /~~ Assistant Engineer
Ward No.

31/12/2014
Assistant Executive Engineer ( )
Bruhat Bangalore Mahanagara Palike

Accounts Superintendent
Bruhat Bangalore Mahanagara Palike

Executive Engineer ( )
Bruhat Bangalore Mahanagara Palike

EXECUTIVE ENGINEER - 2
Bruhat Bangalore Mahanagara Palike,
Dasarahalli Division, Bangalore-57.

ಮುಖ್ಯ ಅಭಿಯಂತರರು